



Serial: RNP-RA/02-0153

OCT 07 2002

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23

MONTHLY OPERATING REPORT

Ladies and Gentlemen:

In accordance with the H. B. Robinson Steam Electric Plant (HBRSEP), Unit No. 2, Technical Specification (TS) Section 5.6.4, "Monthly Operating Reports," and HBRSEP, Unit No. 2, Technical Requirements Manual (TRM) Section 6.2, "Monthly Operating Report," Carolina Power and Light (CP&L) Company submits the enclosed report of operating statistics and shutdown experience for the month of September 2002.

Sincerely,

C. T. Baucom
Supervisor - Licensing/Regulatory Programs

DJS/djs

Attachment

c: NRC Resident Inspector, HBRSEP
L. A. Reyes, NRC, Region II
R. Subbaratnam, NRC, NRR

IE24

MONTHLY OPERATING REPORTDOCKET NO. 050-0261UNIT H. B. ROBINSON STEAM ELECTRIC PLANT (HBRSEP), UNIT NO. 2DATE 10/01/02COMPLETED BY TOM FREEMANTELEPHONE (843) 857-1403

REPORTING PERIOD: SEPTEMBER 2002

1. DESIGN ELECTRICAL RATING (NET MWE): 700.0
2. MAX DEPENDABLE CAPACITY (NET MWE): 683.0

	THIS MONTH	YR TO DATE	CUMULATIVE
3. NUMBER OF HOURS REACTOR CRITICAL	720.00	6551.00	210358.59
4. HOURS GENERATOR ON LINE	720.00	6551.00	207069.26
5. UNIT RESERVE SHUTDOWN HOURS	0.00	0.00	23.20
6. NET ELEC. ENERGY GENERATED (MWH)	505457.00	4609051.00	134940400.00

DOCKET NO. 050-0261
UNIT NAME H. B. ROBINSON STEAM ELECTRIC PLANT (HBRSEP), UNIT NO. 2
DATE 10/01/02
COMPLETED BY TOM FREEMAN
TELEPHONE (843) 857-1403

REPORTING PERIOD: SEPTEMBER 2002

No.	Date	Type F. Forced S. Scheduled	Duration (Hours)	Reason ¹	Method of Shutting Down the Reactor or Reducing Power ²	Cause / Corrective Actions / Comments
N/A	N/A	None	N/A	N/A	N/A	

1

Reason:

A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

2

Method:

1-Manual
2-Manual Scram
3-Automatic Scram
4-Continuation
5- Other (Explain)

SUMMARY: The unit operated at full power the entire month. There were no challenges to the pressurizer power operated relief valves or the pressurizer safety valves during the month. There were no steam generator inspections during the month.